

OIML Pilot Training Center 国际法制计量组织培训中心(示范)

## Training Course on Non-Automatic Weighing Instruments

Ms. <u>Cai Changqing</u> <u>caichq@nim.ac.cn</u> Dr. Wang Jian <u>wjian@nim.ac.cn</u> Dr. Hu Manhong <u>hmh@nim.ac.cn</u> National Institute of Metrology 2016-07-19



## **Brief introduction** Instructors / Participants / course

中国北京 2016年7月18日-22日



## Instructors



Dr. Oliver Mack



Mr. Rene Schoeler



Ms. Cai Changqing



Dr. Wang Jian

中国北京 2016年7月18日-22日



Dr. Hu Manhong



Group	Economy	Name	Organization
	Cambodia	Mr. Vanndeth Yin	National Metrology Center (NMC)
	Colombia	Mr. Diego Rodríguez Joleanes	Superintendencia de Industria y Comercio
1	Egypt	Mr. YASSER METWALLY ABD ELGWAD ELSAYD	ADMINISTRATION OF ASSAY AND WEIGHTS
	China	Ms. Yi Su	Shanghai Institute of Measurement and Testing Technology (SIMT)

Group	Economy	Name	Organization
	Egypt	Ms. Maha Ramadan	ADMINISTRATION OF ASSAY AND WEIGHTS
	Jordan	Mr. Abdulla Gheniemt	Jordan Standard and Metrology Org.
2	R. Korea	Mr. Xiang Yufu	CAS Corporation - China
	China	Mr. Binghui Ma	Zhejiang Provincial Administration of Quality and Technology Supervision



Group	Economy	Name	Organization
	Kenya	Ms. GETRUDE MWAKA NYUNGU	WEIGHTS AND MEASURES DEPARTMENT
	Chinese Taipei	Mr. Hung, Hung Wei	Electronics Testing Center
3	India	Mr. ADITYA PRASAD	INDIAN INSTITUTE OF LEGAL METROLOGY, RANCHI
	China	Mr. Jinchun Zeng	ChongQing Academy of Metrology and Quality Inspection

Group	Economy	Name	Organization
4	Kenya	Mr. Julius Nyamu	Weights and Measures – Kilifi County - Kenya
	Greece	Mr. PANAGIOTIS SOTIROPOULOS	Ministry of Economy, Development & Tourism / General Secretariat of Industry / Directorate of Quality Policy / Section of Metrology Policy
	India	Mr. NITIN MARJARA	INDIAN INSTITUTE OF LEGAL METROLOGY
	China	Ms. Xiyang Wang	SHAANXI INSTITUTE OF METROLOGY SCIENCE



Group	Economy	Name	Organization
	Thailand	Mr. SUDCHAI SRIKHAJORNDET	Central Bureau of Weights and Measures (CBWM)
	Indonesia	Mr. Nugroho Budi Widodo	Directorate of Metrologi
5	Iran	Mr. MOHAMMADREZA HASHEMI ARAGHI	NMCI
	China	Mr. Haitao Wang	Jiangsu Institute of metrology

Group	Economy	Name	Organization
	Iran	Mr. AHAD MOHAMMADI LIVARI	NMCI
	R. Korea	Mr. Jong-Yun KIM	KTC(Korea Testing Certification)
6	Malaysia	Mr. MOHD JUHARI BIN ABDULLAH	MINISTRY OF DOMESTIC TRADE, COOPERATIVE AND CONSUMERISM
	China	Ms. Lina Qu	SHANGHAI YAOHUA WEIGHING SYSTEM CO.,LTD



Group	Economy	Name	Organization
	R. Korea	Mr. Young-Ho JI	KTC(Korea Testing Certification)
7	Mongolia	Ms. Batmend Tudev	Mongolian Agency for Standardization and Metrology (MASM)
,	Singapore	Mr. Andrew Yap Wee Leng	SPRING Singapore
	China Mr.	Mr. Lei Xue	Jiangsu lark weighing apparatus manufacturing co., LTD

Group	Economy	Name	Organization
	Thailand	Mr. THARES YODARLAI	Central Bureau of Weights and Measures (CBWM)
ß	Philippines	Mr. Aries Ordo <b>ñ</b> a	National Metrology Laboratory – Industrial Technology Development Institute
8	Chinese Taipei	Mr. Hwang Hung-Wei	Bureau of Standards, Metrology & Inspection
	Viet Nam	Mr. Cong Vu	Quality assurance and testing center 1 (Quatest 1)



Group	Economy	Name	Organization
	Kazakhstan	Mr. Viktor Milokumov	RSE Kazakhstan Institute of Metrology (KazInMetr)
9	Greece	Mr. FILIPPOS MATSOUKIS	Ministry of Economy, Development & Tourism / General Secretariat of Industry / Directorate of Quality Policy / Section of Metrology Policy
	China	Mr. Tao Huang	National Institute of Metrology
	China	Mr. Kai Jiao	National Institute of Metrology



#### OIML Advisory Group Training Course on Non-Automatic Weighing Instruments 18–22 July 2016 Beijing, China

	09:00-09:45	General introduction of training course and instructors Introduction of each participants Introduction of NIM & Legal Metrology system in China Cai
	09:45-10:30	Introduction of PTB & Legal Metrology system in Europe Oliver
Day 2	10:30-11:00	Coffee break
19 July (Tue)	11:00-12:00	Discusion about the experience of the metrology system in each economy / interests in: Verification, Calibration and Pattern approval
	14:00-14:45	Verification, Calibration and Pattern approval Cai General introduction of OIML R76 Oliver
	14:45-15:30	General Information of NAWI in R76
	15:30-16:00	Coffee break
	16:00-16:45	Modular approach and software examination of weighing instruments



#### OIML Advisory Group Training Course on Non-Automatic Weighing Instruments 18–22 July 2016 Beijing, China

Day 3 20 July (Wed)	09:00-09:45 09:45-10:30 10:30-11:00	Lecture of weighing performance Practical exercise of weighing performance Coffee break
	11:00-12:00	Lecture and practical exercise of repeatbility
	13:00 14:00-16:45	Gathering at the lobby of hotel Technical visit to Sartourius (Beijing)



#### OIML Advisory Group Training Course on Non-Automatic Weighing Instruments 18–22 July 2016 Beijing, China

	09:00-09:45	Lecture of eccentricity
	09:45-10:30	Practical exercise of eccentricity
Day 4	10:30-11:00	Coffee break
21 July (Thu)	11:00-12:00	Lecture and practical exercise of warm-up time
	14:00-16:45	Exam Demonstration of initial verification by each group
	09:00-11:00	Questionnaire
Day 5	11:00-11:30	Issuing certificate of training course
22 July (Fri)	11:30-11:45	Closing ceremony
	13:30-16:00	Tour to Great Wall



# Brief introduction Metrology System / NIM / Mass Lab

中国北京 2016年7月18日-22日



# • Brief Introduction of

- Brief Introduction of NIM & Legal Metrology System in China
- Brief Introduction of PTB & Legal metrology system in Europe
- Discussion about the experience of metrology system in different countries



## Metrology System in China



Users: trade, safety & health, environment protection, industry, transportation.....

## OIML MAA Certificate System in China





## **Campus & facility**



中国北京 2016年7月18日-22日

## Location



#### Mechanics and Acoustics Division He Ping Li campus.

#### Mechanics and Acoustics Division Changping campus.





## **MRA** which NIM involved in







**MRA AQSIQ-METAS** 

#### MAA AQSIQ-OIML







# **Main Facilities**



# Development of Type Evaluation test equipment and project management system for OIML MAA certificate



Recent years, we apply some research projects to develop the type evaluation test equipment and project management system for OIML MAA certificate.



# Development of Type Evaluation test equipment and project management system for OIML MAA certificate



Achievements : 4 Patents, 6 Articles, 1 Registration of Computer Software CopyrightService :Has been carrying out more than 500 pattern evaluation tests and<br/>OIML tests since 2010.

Prize : Won the Second Prize of Science and Technology of AQSIQ in 2013.



#### The whole process of the construction of the mass laboratory











Development of Type Evaluation test equipment since 2009.











#### **Construction of the mass and weighing laboratory**











Thanks to the government increasing support to science and technology, the R&D Funding increased largely. Facilities and environment were much improved.















## Equipment / Force



**300kN Force Standard machine** 



## **Equipment / Force**



20 MN force standard machine



**5 MN force standard machine** 



## Equipment / Force



#### **1 MN force standard machine**





# **Quality System**



## **Quality System**

In 1999, our lab passed the assessment by CNACL, and from then on, NIM has passed Surveillance and Re-assessments conducted by CNACL/CNAS periodically.





## **Quality System**

In order to establish the mutual recognition agreement on pattern evaluation test results, mass and force labs passed the another two on-site assessments which conducted by the experts from NMi and PTB. From 2002 till now, NIM passed the assessment by OIML and passed first and second-round ... peer review by APMP periodically.





#### Management system for Pattern Approval / OIML Certificates



- p Base on the practical experience of our daily management, develop management system for Pattern Approval / OIML Certificates to support our quality system and make it run efficient.
- p The quality system has run for more than 6 years, and it shows that this system is very stable and efficient. This system includes all the general and necessary information of Pattern Approval / OIML Certificates.
- Keep all the related information update in time, in order to help the manager and manufacturer to know the latest situation about the process of the Pattern Approval / OIML Certificates




The electronic documents and Paper documents are one to one correspondence



### Management system for Pattern Approval / OIML Certificates



Till now, this system has stored and shared a great deal of information to us, and it is very convenient and highly effective for us to carry out Pattern Approval in Changping and Hepingli as well.

- n Project of type evaluation 523
- n Working log 411, 954
- n Test Reports 2303
- n Documents from clients 5459
- n E-mails with clients 1903



力学与声学计 量科学研究所	-	任务列表	任务添加	加 查询任	务 任务统计	公共文件	更改密码	邮件提醒	设置	管理 你好:蔡常青	• 注销
	任务列	表									
状态表示:	型批任領	务列表									
■ 进行中 ■ 已完成	年份: 🕻	2014 × 型	比种类: 全	部	✔ 状态: 全部	~					
	北本	4条号	而日编号	在冬 <del>米</del> 刑	心哭夕我	单位复杂			伯吉人		
■ 整改中		5012014003	14-LS-	委托型批	定角式雷达测速仪 HT3000	杭州来涞科技	有限公司		杜磊 4623	查看详细	
		1002014076	14-LS- 148	委托型批	<b>配料秤 PL1600</b>	群峰智能机械	服份公司		王健 4609	查看详细	
資料审查		1002014075	14-LS- 147	委托型批	水泥秤 DCS-500	群峰智能机械	服份公司		王健 4609	查看详细	
		1002014074	14-LS- 141	委托型批	电脑组合秤BS系列	佛山市博伦斯	机电有限公司		王健 4609	查看详细	
Status:		2002014011	14-LS- 138	委托型批	称重传感器PR系列	赛多利斯工业	(称重设备(北京	)有限公司	吴鲲 4618	查看详细	
Finished		1002014073	14-LS- 139	委托型批	矿用电子皮带秤ICS- 17J5	北京市煤炭矿	"用机电设备技术	开发公司	王健 4609	查看详细	
Canceled Modifying		2002014010	ZL-010	资料审查	称重传感器 TSH	梅特勒-托利約	多(常州)精密份	《器有限公司	吴鲲 4618	查看详细	
Alarm		1002014072	14-LS- 137	委托型批	定重包装机 TLD- K50/D	合肥托利多自	动化科技有限公司	3	王健 4609	查看详细	
Document Review		1002014071	14-LS- 128	委托型批	动态汽车衡DCS- 30KII	北京万集科技	服份有限公司		王健 4609	查看详细	
		1002014070	14-LS- 127	委托型批	称重显示器 XK315A1-2X	上海彩信电子	有限公司		王健 4609	查看详细	
		1002014069	14-LS- 126	委托试验	自动定里秤DCS型系 列	无锡市瑞利技	末开发有限公司		王健 4609	查看详细	
		4012014002	14-LS- 124	委托型批	声级计 G 系列	上海英波声学	工程技术有限公司	3	牛锋 4630	查看详细	
		2002014009	ZL-009	资料审查	称重传感器SLB515	梅特勒-托利约	多(常州)精密的	(器有限公司	吴鲲 4618	查看详细	
		1002014068	ZL-008	资料审查	价格标签秤TM-30H	上海大华志美	电子有限公司		王健 4609	查看详细	
		1002014067	14-LS- 118	委托型批	电子天平 EP/ES系列	瑞士 Precisa Precisa Gra	(普利塞斯)普利 vimetrics AG	北東京公司	王健 4609	查看详细	
			共	有 92 项任务	第 1/7	页		下一页 尾页			
	新建任	务									
	-6	任务列表	任务添加	查询任务		更改密码	邮件提醒设置	5 管理			

力学与声学计 量科学研究所		任务列表	任务添加	n 查询任 <del>:</del>	务 任务统计	公共文件	更改密码	邮件提醒	设置	管理 你好:蔡常青	注销
	任务列	刘表									
状态表示:	型批伯	[务列表									
🗾 进行中	年份:	2012 🗸 펠	比种类: 全	部	✔ 状态: 全部	~					
10000000000000000000000000000000000000							Provide the state	2020in			
	状态	任务号	项目编号	任务类型	仪器名称		单位名	称	负责人		
■ 200中		1002012142	12-LS- 252	委托型批	定量包装机ZKYT-J	LM-50K-X	江苏中有限公	科友特机器人科技	E 王健 4609	查看详细	
整改完成		1002012141	12-LS- 251	非重大	电子天平ML系列		梅特勒 海)有	)-托利多仪器(上 限公司	姚弘 4635	查看详细	
●●		1002012140	12-LS- 250	非重大	电子天平JE系列		梅特勒 海)有	)-托利多仪器(上 限公司	姚弘 4635	查看详细	
		1002012139	12-LS- 249	非重大	电子天平MS系列		梅特勒 海) 有	]-托利多仪器(上 限公司	丁京安 4634	查看详细	
		1002012138	12-LS- 248	非重大	电子天平MS系列		梅特勒 海) 有	)-托利多仪器(上 限公司	丁京安 4634	查看详细	
		1002012137	12-LS- 247	非重大	电子天平MS系列		梅特勒 海)有	)-托利多仪器(上 限公司	钟瑞麟 4635	查看详细	
		1002012136	12-LS- 246	非重大	电子天平MS系列		梅特勒 海) 有	)-托利多仪器(上 限公司	胡满红 4609	查看详细	
		1002012135	12-LS- 245	委托型批	电脑定量包装秤DC	5系列	无锡市限公司	) 衡瑞自动化科技有	i 王健 4609	查看详细	
Example: Project	14	1002012134	12-LS- 244	委托型批	混凝土配料机 PLD8	00/PL1600QB	維坊方	建建设机械厂	王健 4609	查看详细	
1002012132		1002012133	12-LS- 241	OIML	称重指示器YH-T7、	YH-T7+E	上海橋司	华称重系统有限公	钟瑞麟 4635	查看详细	
Manufacturer :		1002012132	12-LS- 239	委托型批	电子皮带秤MDL-17 机MDL-30X	7/皮带称重式给料	+ (煤) 徐州妻 有限公	; 迪隆机械电子设备 ☆司	· 王健 4609	查看许细	
Shanghai YAO		1002012131	ZL-022	资料审查	射频识别计价秤		成都九份有限	,洲电子信息系统服 公司	t 王健 4609	查看详细	
System	100	1002012130	12-LS- 237	委托型批	便携式动态轴重仪P	DQ-30A	河北诸司	恒电子科技有限公	: 王健 4609	查看详细	
Company		1002012129	12-LS- 236	委托型批	电子定量包装秤DC	5	安徽永限公司	<成电子机械技术有	ī 王健 4609	查看详细	
		1002012128	12-LS- 235	委托型批	称重机 YLTC		青岛英公司	力特包装机械有限	王健 4609	查看详细	
			共有	154 项任务	第 1/1	1 页	- Construction	下一页 尾页			
	新建住	琦									
		任务列表	任务添加	查询任务 Copyrigh	任务统计 公共文件 ht © 2009 力学与产学计	更改密码   量科学研究所	邮件提醒 设计	置管理			

#### 力学与声学计 量科学研究所

#### 任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常青 注销

任务列表 》 任务添加 》 任务详细

**Project No:** 任务号: 1002012133

22334 12 28

**Basic Information:** 

#### **Task Type**

**Person in Charge** 

Instrument:

Classification<

Manufacturer

**Contact Person** 

Charge

**Task Receiving Time** 

**Finished Time** 

是本信息					
型批种类:	100 衡器	任务类型:	OIML	任务说明:	全性能
项目编号:	12-LS-241	负责人:	钟瑞麟	联系电话:	4635
任务来源:	国家质量监督检验检疫	总局	申请书编号:	OIML-12-09号	
仪器名称:	称重指示器YH-T7、YI	H-T7+E			
仪器种类:	非自动衡器	仪器子类:	非自动衡器模块	档案盒:	2012-115
单位名称:	上海耀华称重系统有限	公司			
联系人及电话:	翟莉娜 021-6728280	00-869		费用:	40000
接到任务日期:	2012-12-27	收样机日期:	2013-1-18	任务完成日期:	2013-5-21
试验任务:	📕 已完成 🛛 🗿	资料审查 常温试	验 环境试验 E	MC试验	
相关操作:	<b>国</b> 打印				

该任务作为资料审查任务(任务号: ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915, email: qubaolina@163.com)

2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试验费用(邮件已发)。

2013年1月8日厂家交纳了试验费用。

2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人员瞿莉娜(15921215915)需派人员到计量 院安装调试样机。

2013年1月18日,曾张元等来计量院安装调试好样机。

5W: 该仟务作为资料审查仟务(仟务号:ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 When, Who, Where, 莉娜 (15921215915, email: gubaolina@163.com) Why, What All the information 2012年12月31日10:40申话通知厂家人员寄送样机,并交纳试验费用(邮件已发)。 here recorded during 2013年1月8日厂家交纳了试验费用。 the former document 2013年1月10日11:22收到企业邮寄的样机, 11:25通知企业人员瞿莉娜(15921215915)需派人员到计量 review and later 院安装调试样机。 instrument testing. 2013年1月18日,曾张元等来计量院安装调试好样机。 2013年1月18日10:40,进行罟零范围、除皮等功能核查。2013年1月21日收到企业人员瞿莉娜 (15921215915, email: qubaolina@163.com)发来的技术资料。 When received the EUT? 2013年1月21日11:35,进行YH-T7和YH-T7+E辐射场试验,16:10结束,结论合格。样机1(YH-T7): 2013年1月30日10: 50,对样机进行静放电试验(直接施加),11: 15进行静放电试验(间接施加),结论 Who came to install the 合格。 EUT? 2013年2月5日9:10进行电压跌落试验,10:00进行电脉冲群试验,10:10进行浪涌试验,11:45进行传 Where is the test place? 导射频场抗扰度试验,结论合格。因模拟器K3607均在用,其他试验拟在2013年2月底进行。 2013年2月18日11:32至11:47,进行首次称量、首次量稳测试。16:14至16:16,进行首次20度温度试 Why the task last for a 验。 long time? 2013年2月19日9:02至9:04,进行40度温度试验,16:05至16:07,进行0度温度试验。 What tests should be 2013年2月20日9:14至9:16,进行5度温度试验,16:16至16:18,进行末次20度温度试验。 done? 2013年2月21日8:54,进行第2次量程稳定性测试。 2013年2月22日9:20,进行第3次量程稳定性测试,15:57至15:59,进行初始20度湿热试验。 2013年2月25日10:07至10:09,进行40度湿热试验,在0.4、0.5、0.6mV/V载荷处修正误差为-0.6e、-0.8e、-0.9e,均超过mpe(为0.5e、0.5e、0.75e),结论超差。 2013年2月25日15:53至15:55,进行20度湿热测试,结论仍然超差。 2013年2月27日10:32,第5次量程稳定性测试。 备注: 2013年3月4日8:32至8:34,重新进行了标定,进行了首次20度湿热试验。 2013年3月6日11:08至11:10,进行了40度湿热试验,17:09至17:11,进行了末次20度湿热试验。 2013年3月7日16:32,进行了第6次量程稳定性测试。 2013年3月8日14:05,进行重复性测试,14:15至14:19,进行皮重测试。 2013年3月11日9:27至10:07,进行预热时间测试,16:08,进行第7次量程稳定性测试。

该任务作为资料审查任务(任务号:ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915,email: qubaolina@163.com)

2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试验费用(邮件已发)。

2013年1月8日厂家交纳了试验费用。

2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人员瞿莉娜(15921215915)需派人员到计量 院安装调试样机。

2013年1月18日,曾张元等来计量院安装调试好样机。

2013年1月18日10:40,进行置零范围、除皮等功能核查。2013年1月21日收到企业人员瞿莉娜 (15921215915,email: qubaolina@163.com)发来的技术资料。

2013年1月21日11:35,进行YH-T7和YH-T7+E辐射场试验,16:10结束,结论合格。样机1(YH-T7): 2013年1月30日10:50,对样机进行静放电试验(直接施加),11:15进行静放电试验(间接施加),结论 合格。

2013年2月5日9:10进行电压跌落试验,10:00进行电脉冲群试验,10:10进行浪涌试验,11:45进行传 导射频场抗扰度试验,结论合格。因模拟器K3607均在用,其他试验拟在2013年2月底进行。

2013年2月18日11:32至11:47,进行首次称量、首次量稳测试。16:14至16:16,进行首次20度温度试验。

2013年2月19日9:02至9:04,进行40度温度试验,16:05至16:07,进行0度温度试验。

2013年2月20日9:14至9:16,进行5度温度试验,16:16至16:18,进行末次20度温度试验。

2013年2月21日8:54,进行第2次量程稳定性测试。

2013年2月22日9: 20,进行第3次量程稳定性测试,15: 57至15: 59,进行初始20度湿热试验。

2013年2月25日10:07至10:09,进行40度湿热试验,在0.4、0.5、0.6mV/V载荷处修正误差为-0.6e、-

0.8e、-0.9e,均超过mpe(为0.5e、0.5e、0.75e),结论超差。

2013年2月25日15:53至15:55,进行20度湿热测试,结论仍然超差。

A注: 2013年2月27日10:32,第5次量程稳定性测试。

2013年3月4日8:32至8:34,重新进行了标定,进行了首次20度湿热试验。

2013年3月6日11:08至11:10,进行了40度湿热试验,17:09至17:11,进行了末次20度湿热试验。

2013年3月7日16:32,进行了第6次量程稳定性测试。

2013年3月8日14:05,进行重复性测试,14:15至14:19,进行皮重测试。

2013年3月11日9:27至10:07,进行预热时间测试,16:08,进行第7次量程稳定性测试。

2013年2月21日8:54, 进行第2次量程稳定性测试。 2013年2月22日9:20,进行第3次量程稳定性测试,15:57至15:59,进行初始20度混热试验。 2013年2月25日10:07至10:09,讲行40度湿热试验,在0.4、0.5、0.6mV/V载荷处修正误差为-0.6e、-0.8e、-0.9e,均超过mpe(为0.5e、0.5e、0.75e),结论超差。 2013年2月25日15:53至15:55, 进行20度湿热测试, 结论仍然超差。 2013年2月27日10:32,第5次量程稳定性测试。 备注: 2013年3月4日8:32至8:34,重新进行了标定,进行了首次20度湿热试验。 2013年3月6日11:08至11:10,进行了40度湿热试验,17:09至17:11,进行了末次20度湿热试验。 2013年3月7日16:32,进行了第6次量程稳定性测试。 2013年3月8日14:05, 进行重复性测试, 14:15至14:19, 进行皮重测试。 2013年3月11日9:27至10:07,进行预热时间测试,16:08,进行第7次量程稳定性测试。 2013年3月12日15:40, 进行第8次量程稳定性测试。 2013年3月13日12:07,讲行电源电压变化测试,13:02,讲行平衡稳定性测试。 样机2(YH-T7+E): 2013年1月30日11: 55,对样机进行静放电试验(直接施加),12: 20进行静放电试验(间接施加),结论 合格。 2013年2月5日9:10进行电压跌落试验,10:00进行电脉冲群试验,10:10进行浪涌试验,11:45进行传 导射频场抗扰度试验,结论合格。因模拟器K3607均在用,其他试验拟在2013年2月底进行。 2013年2月18日11: 10至11:19,进行首次称量、首次量稳测试。16:10至16:12,进行首次20度温度试 验。 2013年2月19日8:57至8:59,讲行40度温度试验,16:09至16:11,讲行0度温度试验。 2013年2月20日9:18至9:20,讲行5度温度试验。,16:07至16:09,讲行末次20度温度试验。 2013年2月21日8:56, 进行第2次量程稳定性测试。 2013年2月22日9:22,进行第3次量程稳定性测试。16:04至16:06,进行初始20度混热试验。 2013年2月25日10:12至10:14,讲行40度混热试验,结论合格,15:48至15:50,讲行20度混热试验,结论 合格。 2013年2月26日13:47,第4次量程稳定性测试。 2013年2月27日10:30,第5次量程稳定性测试,13:12,进行重复性测试,13:20至13:23,进行皮重测 试。2月27日10:10至10:40,预热试验,16:10,讲行第6次量程稳定性测试。 2013年3月1日15:21,进行第7次量程稳定性测试。 2013年3月4日8:57,进行第8次量程稳定性测试。 2013年3月13日12:10,进行电源电压变化测试,13:15,进行平衡稳定性测试。3月29日14:20,进行称重 仪表外接电缆长度测试。

	任务进程									
Task progress:	实	佥室试验至样机接·	妆时间:	54天			已完成			
Time for receiving EUT:	ì	式验报告至样机接	妆时间:	94天			已完成			
From receiving EUT to Test Report :	试验报告至任务接收时间: 1			116天 日		已完成				
	资料审查									
Document Review:		接收日期: 201	2-12-2	7			资料审查人:	钟瑞麟		
Document List : Application Form, Photo, Drawing, Manual,	<ul> <li>☑申请表 ☑照片 ☑图纸 ☑电路设计图 ☑说明书 □软件流程图 □检测标准 □测试报告 □传感器报告 ☑铭牌</li> </ul>									
	资料审查联系 (联系厂家并发送产	2-12-3	1	完成日			月: 2012-12-31			
	审查备注:	审查备注: 该任务作为资料审查任务(任务号: ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915,email: qubaolina@163.com)								
	样机接收									
EUT Receive: Notice Date Manufacturer Feedback	通知日期 <b>:</b> 20	)12-12-31		厂家反馈备注	2012 验费月 2013 2013 员瞿末 2013	年12月31 月(邮件已 年1月8日/ 年1月10日 前娜(159) 年1月18日	日10:40电话通 发)。 「家交纳了试验碧 ]11:22收到企业 21215915)需 ],曾张元等来计	知厂家人员寄送样机 费用。 '邮寄的样机,11:2 派人员到计量院安装 '量院安装调试好样'	l,并交纳试 25通知企业人 表调试样机。 机。	
	☑传感器 ☑仪表	□承重框架□	其它关键	部件	收样机	1日期(以	装好样机并交费的	的最后日期为准):	2013-1-18	
	实验室试验									
	常温试验完成日期:	2013-3-13	环境试验	佥完成日期:	2013-2	-25 E	MC试验完成日期	明: 2013-2-5		
	试验报告		3		112. No.	- 60 		in .		
	报告编写人员:	王肖磊	试验报告	告开始日期:	2013-4	-7 นั	成验报告结束日期	月: 2013-4-22		
	报告审核人员1:	钟瑞麟	试验报告	告审核日期:	2013-5	-15				
	报告审核人员2:		试验报告	皆审核日期:						
	报告提交人员:	钟瑞麟	试验报告	告提交日期:	2013-5	-21	(任务完成日期)			

	审查备注:									
	样机接收									
Laboratory Test : Ambient Test Time	通知 <b>曰期:</b> 2	通知曰期:2012-12-31		2012年12月3 验费用(邮件 2013年1月8 2013年1月10 员瞿莉娜(15 2013年1月18	2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试 验费用(邮件已发)。 2013年1月8日厂家交纳了试验费用。 2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人 员瞿莉娜(15921215915)需派人员到计量院安装调试样机。 2013年1月18日,曾张元等来计量院安装调试好样机。					
Environment Test Time EMC Test Finished Time	☑传感器 ☑仪表	☑传感器 ☑仪表 □承重框架 □其它关键部件 收样机日期(以装好样机并交费的最后日期为准):2013-:								
	实验室试验									
	常温试验完成日期:	2013-3-13	环境试验完成日期:	2013-2-25	EMC试验完成日期:	2013-2-5				
	试验报告									
Test Report :	报告编写人员:	王肖磊	试验报告开始日期:	2013-4-7	试验报告结束日期:	2013-4-22				
Report Writer	报告审核人员1:	钟瑞麟	试验报告审核日期:	2013-5-15						
Report Reviewer Report Submitter	报告审核人员2:		试验报告审核日期:							
Report Review Remark	报告提交人员:	钟瑞麟	试验报告提交日期:	2013-5-21	(任务完成日期)					
	报告备注:									
	报告审查备注:	王肖磊2013.4.8% 少电缆长度测试。 评大纲讨论,钟于 致,后统一。温度 内容。重新计算了 砝码编号和K3607	7步录入报告后,发现 后安排胡满红进行相 2013年5月14~15日 及试验试验的记录存 最大电缆长度。更新 编号,修改了平横稳	见同一天的浪涌试 关的测量工作,于 日审核通过。主要 在问题,最大点的 了静电放电照片。 定性描述。	验大气压不一致,且平 -4月22日完成。之后[ 存在的问题:电磁试验 时间和最终时间应一部 5月16日,胡满红修	平衡稳定性试验数据有问题,缺 由于出差、公益项目验收、型 验的细分显示与平衡稳定性不一 致。修改了核查表中标记相关 验核对了页码,修改了标准器				
Related Document	编辑任务相关文件	结果文件 往来		务删除任务	返回列表 86件開醒 设置 管理					

量科学研究所	任务列表 任务添加 查询任务 任	务统计 公共文件 更改	文密码 邮件	提醒 设置 管	理你好:蔡
	任务列表 》 任务添加 》 相关文件				
	相关文件管理				
ocument List :	上海耀华称重系统有限公司--称重指示器YH-	T7、YH-T7+E			
	文件列表				
pplication Form,	文件名称	下载  文件大小	文件类型	添加人	删除
noto,	12-LS-241申请资料	2.67 MB	.pdf	dust	
rawing,	04型式评价样机交接单-上海耀华	39 КВ	.doc	wangjian	1
anual,	耀华设置	🕥 11 КВ	.xls	humanhong	Ē
ain parts list	YH-T7(+E) OIML 认证资料(20121016)	() 12.01 MB	.zip	zhongrl	
	辐射场试验2013-1-21	15.98 MB	.rar	renxp	
	T7(+E)主要元器件清单	🥥 зо кв	.xls	zhongrl	1
	仪表测试电缆长度-耀华	27 КВ	.xls	humanhong	1
	YH-T7+E静电放电照片	() 4.95 MB	.zip	humanhong	
	YH-T7静电放电照片	6.3 MB	.zip	humanhong	1
	YHT7照片	0.57 МВ	.JPG	humanhong	1
	铅封照片	0.57 МВ	.JPG	humanhong	1
	YH-T7+ E照片	0.55 МВ	.JPG	humanhong	
	耀华7+E	() 0.54 MB	.jpg	zhongrl	1
	<b>耀华7</b>	0.55 МВ	.jpg	zhongrl	1
		J. 10 14	- CI	1	

#### 力学与声学计 量科学研究所

#### 任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常青 注销

#### 任务列表 ≫ 任务添加 ≫ 相关文件

#### 相关文件管理

文件列表

#### 上海耀华称重系统有限公司--称重指示器YH-T7、YH-T7+E

#### **Application of OIML**

人口中的					ζĤ		
12-LS-241申请		型式评价	试验任务书		.6		中国語句, gont - P -
04刑士证价样和	项目编号	12-LS-241			0	OWIL	manual of approximation.
<sup>半</sup> 坐设置	<ul> <li>特別透明。</li> <li>技到任务书/ 起计)内光3</li> <li>よ約以上在</li> </ul>	后,任务承接人参强在 &全部工作,并将该任务	五十五十工作日(如雾试 5-1及型式评价试验报告号 68、异位及往母亲笔在文	输,自载频样机之日 转有关文件报业各作。 文件诗行环路审核后	1		OIML 合态证书申请表
(H-T7(+E) OI	鉴学,并对	文件中的试验项目, 技	术数据灵结论负责。	ATT SALET THE PARE	2.		Application of OIML Certificate
	任务朱谱	国家沃量原香植植	检查意则			中诸羊在名称。	上直螺导体观察所有限公司
翻场试验201	中语传输号	OIML-12-09 号			5.	Nerve of Applicant	Storybei Natiwo Weighing System Co., LTD
	卑 佗 名 府	上海疆华称派系统	有限会司		H	图45	中国
7(+E)主要元言	仪器名符	称重数示器 YH-17	, YH-17+Е		0	Name of Country:	China
()主知らざ由 然上	联系人及电话	- 张系人及电话 標款線 021+67282800-869				HUE-	上均也成美国区土壤等4659号
XXXXIIIIHESUIK	申请书	1.67	产品资料	日度	1	Allesia	No. 0199, Shorgson Rd. Padeng Dorrict. Murghus
H-T7+E静电方	试验单位	(B);			.9	estado bie 9% a	200124
20 A. 2000 A. 20	1.收到试验样核	和日期	3.试验报告完成日期			Pest Corde	200124
H-T7静电放电	2.全部试验完4	化日期	4.結算(交賣)日期		.3	电话	021-07282800-809
HT7照片	结论, 我实情	建玉乐操作留下运的运	间型式评价试验任务已	全部完成。坦	.5	Tel (C.K.	121-67282800-869 021-38860003
品封照片	论1合称45	世式评价试验报告等有 3	(美文件尖通过了严格审 (美文件尖通过了严格审	栈,建议签发。	.5	For: 自意人,(筆字)	0(1.5350005 Feast ghadragitsLoon
YH-T7+E照片			4	<b>月</b> 月	.5	电图Art (第77)	A STAR
擢华7+E						Signature of Talson	C. Street
耀华7	W 72					中闭目闭。 28) Desc Facylication	2. 10-16

#### 任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 Copyright © 2009 力学与声学计量科学研究所

该任务作为资料审查任务(任务号:ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915,email: qubaolina@163.com)

#### 样机接收

审查备注:

A TRANSPORT PROPERTY AND

通知日期:	2012-12-31	厂家反馈备注:	2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试 验费用(邮件已发)。 2013年1月8日厂家交纳了试验费用。 2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人 员瞿莉娜(15921215915)需派人员到计量院安装调试样机。 2013年1月18日,曾张元等来计量院安装调试好样机。
☑传感器 ☑仪3	表 🗌 承重框架 🔲 其它美	<b>关键部件</b>	收样机日期(以装好样机并交费的最后日期为准):2013-1-18
and the second second			

头短至叫短	1	4	P.		
常温试验完成日期:	2013-3-13	环境试验完成日期:	2013-2-25	EMC试验完成日期:	2013-2-5
试验报告					
报告编写人员:	王肖磊	试验报告开始日期:	2013-4-7	试验报告结束日期:	2013-4-22
报告审核人员1:	钟瑞麟	试验报告审核日期:	2013-5-15		
报告审核人员2:		试验报告审核日期:			
报告提交人员:	钟瑞麟	试验报告提交日期:	2013-5-21	(任务完成日期)	
报告备注:					
报告审查备注:	王肖磊2013.4 少电缆长度测证 评大纲讨论,钟 致,后统一。温 内容。重新计算 砝码编号和K30	.8初步录入报告后,发现 、。后安排胡满红进行相 中于2013年5月14~15 建度及试验试验的记录存 【了最大电缆长度。更新 507编号,修改了平横稳	见同一天的浪涌试  关的测量工作, 日审核通过。主要 在问题,最大点  了静电放电照片  愈定性描述。	战验大气压不一致,且平 于4月22日完成。之后 更存在的问题:电磁试验 的时间和最终时间应一 。 5月16日,胡满红俏	平衡稳定性试验数据有问题,制 由于出差、公益项目验收、型 验的细分显示与平衡稳定性不一 致。修改了核查表中标记相关 验核对了页码,修改了标准器

扁嶺任务 相关文件 结果文件 往来文件 **Final Document** 新建任务 返回列表 删除任务 邮件提醒 设置 管理 任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 Copyright © 2009 力学与声学计量科学研究所

#### 力学与声学计 量科学研究所

任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常青 注销

任务列表 》 任务添加 》 试验结果文件

#### 试验结果文件管理

#### 上海耀华称重系统有限公司--称重指示器YH-T7、YH-T7+E

#### 文件列表

文件名称	下载	文件大小	文件类型	添加人	明除
上海耀华YH-T7-wxl-zhong		3.88 MB	.xls	zhongrl	Ē
上海耀华YH-T7+E-wxl-zhong		3.94 MB	.xls	zhongrl	1
上海耀华YH-T7 E-wxl-zhong-hmh	0	4.49 MB	.xls	humanhong	1
上海耀华YH-T7-wxl-zhong-hmh	0	4.45 MB	.xls	humanhong	1
上海耀华YH-T7 E-wxl-zhong-hmh-YH-wxl	0	4.49 MB	.xls	dust	1
上海耀华YH-T7-wxl-zhong-hmh-YH-wxl	0	4.35 MB	.xls	dust	1
上海耀华YH-T7-wxl-zhong-hmh-YH	0	0.56 MB	.pdf	zhongrl	1
上海耀华YH-T7 E-wxl-zhong-hmh-YH	0	0.58 MB	.pdf	zhongrl	1
上海耀华YH-T7 E-wxl-zhong-hmh-YH-zhong	0	4.49 MB	.xls	zhongrl	1
上海耀华YH-T7-wxl-zhong-hmh-YH-zhong	0	4.35 MB	.xls	zhongrl	1
型评报告上交记录241	0	0.26 MB	.pdf	dust	1
OIML-1303	0	4.15 MB	.pdf	dust	1
OIML-1304	0	4.66 MB	.pdf	dust	1
上海耀华YH-T7 E打印版(2014年01月20日确认)	0	4.43 MB	.xls	zhongrl	1
上海耀华YH-T7打印版(2014年1月20日确认)	Re	4.4 MB	.xls	zhongrl	T
	5	7			

#### 添加试验结果文件



#### 力学与声学计 量科学研究所

#### 任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常青 注销

任务列表 ≫ 任务添加 ≫ 试验结果文件

#### 试验结果文件管理

#### 上海耀华称重系统有限公司--称重指示器YH-T7、YH-T7+E

又件名称			B.而然为天服		、载	Report page 2 / 18
上海耀华YH-T7-		National Institute 18th,Bei San Huar	of Metrology Dong Ja,Beijing P.R.Cl	AA		GENERAL INFORMATION CONCERNING THE TYPE Application M <sup>+</sup> 0ML-1228
_海耀华YH-T7-	RIFT					Vype lexignerom Manufacturer Shanghe Verkus Weghing System Co., 21D Applicant Discipling Indicaso Instrument datagory
海耀华YH-T7						Complete instrument (x) Module (1) with the error function (x = 0.5 Anoranacy obset
_海耀华YH-T7-		TEST	REPORT			In Self- Serf-self- Non-self-adicating
「海火線化シロニエフ」		Nº NB	LSmc-1303		<b>S</b>	an [1,1]" Maco
			n the			sa Uzsa da na
:海耀华YH-T7-		Type Examinat	iou ef an Indicator			10 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -
_海耀华YH-T7-						"Loup" 250 V Live" / V Live" / V In 55 Hz Barsey Linen" () v "note: for logs voltage see near page. Zens-sering cavies. The sevice:
·海耀华YH-T7	Type:	YH-T7				Nonsucorasc 🛛 🕅 Tare balancing Combined sectors device
	Manufactu	ire: Shanghai Yaoh	aa Weighing System			N Semi-automatic Tex salpting
海耀华YH-T7		ConLID			9	Automatic perc-setting Preset tere device  Initial zero-setting X Subtractive tere
_海耀华YH-T7-						X Zero-Insking Additive tare
明矾 坦牛 日本 记号						initial zero-setting range = <u>e10</u> % of Max Temperature range: <u>0, 40</u> % Peinter: <u>Built-in</u> <u>Cammacted</u> Hom present <u>in</u> Ho connection
EMIKALXUN	The true was	tested under the follow	int requirements		-	bot connectable
DIML-1303	R76-1,edition	n 2006(E)				Identification Processor Million Academic Social Constraints     Social Constraints
DIML-1304						Insertaces (punter, tarue) / Classification (punter) (3)
上海耀华YH-T7	This report is	actuoes 35 pages.				Evaluation period 2015-121-2015-4-8 Disk of Neorth 2015-4-8 Observer: He Manhang Zhong Rules
上海耀华YH-T7非	▲会司表加回照					単合可決地回転
动动动给果文件						
			3			
	测	览 上传				

该任务作为资料审查任务(任务号:ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915,email: qubaolina@163.com)

#### 样机接收

审查备注:

a transferry work in some

通知日期:	2012-12-31	厂家反馈备注:	2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试 验费用(邮件已发)。 2013年1月8日厂家交纳了试验费用。 2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人 员瞿莉娜(15921215915)需派人员到计量院安装调试样机。 2013年1月18日,曾张元等来计量院安装调试好样机。
☑传感器 ☑仪3	表 □承重框架 □其它关	<b>关键部件</b>	收样机日期(以装好样机并交费的最后日期为准): 2013-1-18

#### 

大拉主动拉	4	4	12	+	10
常温试验完成日期:	2013-3-13	环境试验完成日期:	2013-2-25	EMC试验完成日期:	2013-2-5
试验报告		20 			
报告编写人员:	王肖磊	试验报告开始日期:	2013-4-7	试验报告结束日期:	2013-4-22
报告审核人员1:	钟瑞麟	试验报告审核日期:	2013-5-15		
报告审核人员2:		试验报告审核日期:			
报告提交人员:	钟瑞麟	试验报告提交日期:	2013-5-21	(任务完成日期)	
报告备注:					
报告审查备注:	王肖磊2013.4. 少电缆长度测试 评大纲讨论,钟 致,后统一。温 内容。重新计算 砝码编号和K36	8初步录入报告后,发现 。后安排胡满红进行相 于2013年5月14~15 度及试验试验的记录存 了最大电缆长度。更新 07编号,修改了平横稳	见同一天的浪涌试  关的测量工作,引 日审核通过。主要  在问题,最大点的  了静电放电照片。  愈定性描述。	验大气压不一致,且平 F4月22日完成。之后( 存在的问题: 电磁试验 的时间和最终时间应一 5月16日,胡满红修	平衡稳定性试验数据有问题,缺 由于出差、公益项目验收、型 这的细分显示与平衡稳定性不一 致。修改了核查表中标记相关 验核对了页码,修改了标准器



力学与声学计 量科学研究所

任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常青 注销

#### 往来文件管理(投诉、咨询)

文件列表

#### 上海耀华称重系统有限公司--称重指示器YH-T7、YH-T7+E

Communication Document List

文件名称	下载	文件大小	文件类型	添加人	删除
转发 Re上海耀华-型式试验样机寄送地址及交费信息	$\bigcirc$	42 KB	.msg	dust	Ē
答复 上海耀华 OIML认证资料电子档	0	0.01 KB	.txt	dust	1
转发 上海耀华 OIML认证资料电子档	Ste	12.12 MB	.msg	dust	1
转发 Re答复 上海耀华 OIML认证资料电子档	<b>S</b>	53 КВ	.msg	dust	1
耀华OIML确认表	0	74 KB	.msg	dust	1
上海耀华称重系统有限公司-称重指示器-资料准备	0	0.1 MB	.msg	dust	1

添加往来(投诉、咨询)文件

浏览... 上传

返回

任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理

Copyright © 2009 力学与声学计量科学研究所

力学与吉学计		
量科学研究所	図        ・ <t< th=""><th></th></t<>	
	文件 邮件 开发工具 Adobe PDF	~ ?
	发件人: 钟瑞麟 <zhongrl@nim.ac.cn></zhongrl@nim.ac.cn>	发送时间: 2013-1-21 (周一) 13:07
	C 收件人: 衡器型评	
Email with client		
i	发件人: qulina [qubaolina@163.com]	
	发送时间: 2013 年 1 月 19 日 14:53	
	1) 判: 钾瑞麟; <u>sea in heart@139.com</u> 主題・上海纓化 OIMI 法证资料由子档	
	, 钟博士,	
	附件为我公司 T7(+E)OIML 认证资料电子档,请查阅。辛苦了。有问题请联系我。	
	H	
	- 祝好!	
3	3.	
	上海耀华称重系统有限公司	
	<sup>11</sup> 瞿莉娜	
	Add: 上海市闵行区沈杜路 4239 号	
	TEL: 021-67282800/01/02 转 869 分机	
	Fax : 021-58860003	
	▲ 查看以下用户的更多信息: 钟瑞麟。	

力学与声学计 量科学研究所

任务列表 任务添加 查询任务 任务统计 公共文件 更改密码 邮件提醒 设置 管理 你好:蔡常菁 注销

任务列表 👂 任务添加 👂 任务详细

任务号: 1002012133

1-	住白
44	10.22

型批种类:	100 衡器	任务类型:	OIML	任务说明:	全性能
项目编号:	12-LS-241	负责人:	钟瑞麟	联系电话:	4635
任务来源:	国家质量监督检验检疫总局 申请书编号: OIML-12-09号				OIML-12-09뮥
仪器名称:	称重指示器YH-T7、YH-T	称重指示器YH-T7、YH-T7+E			
仪器种类:	非自动衡器	仪器子类:	非自动衡器模块	档案盒:	2012-115
单位名称:	上海耀华称重系统有限公司	司			
联系人及电话:	翟莉娜 021-67282800-869			费用:	40000
接到任务日期:	2012-12-27	收样机日期:	2013-1-18	任务完成日期:	2013-5-21
试验任务:	🔡 已完成 资料	ERC试验 资料审查 常温试验 环境试验 EMC试验			
相关操作:	<mark>∟</mark> 打印				
	该任务作为资料审查任务(任务号:ZL-020)于2012年11月22日-11月26日进行了资料审查。厂家人员为瞿 莉娜(15921215915,email:qubaolina@163.com) 2012年12月31日10:40电话通知厂家人员寄送样机,并交纳试验费用(邮件已发)。 2013年1月8日厂家交纳了试验费用。 2013年1月10日11:22收到企业邮寄的样机,11:25通知企业人员瞿莉娜(15921215915)需派人员到计量 院安装调试样机。 2013年1月18日,曾张元等来计量院安装调试好样机。				
	2013年1月18日10:40,进行置零范围、除皮等功能核查。2013年1月21日收到企业人员瞿莉娜 (15921215915,email: qubaolina@163.com)发来的技术资料。				



### **Brief introduction** Type Evaluation / Verification / Calibration



n Type (pattern) evaluation: conformity assessment procedure on one or more specimens of an identified type (pattern) of measuring instruments which results in an evaluation report and / or an evaluation certificate (VIML 2.04)

n Type approval: decision of legal relevance, based on the review of the type evaluation report, that the type of a measuring instrument complies with the relevant statutory requirements and results in the issuance of the type approval certificate (VIML 2.05)











Verification: provision of objective evidence that a given item fulfils specified requirements(JCGM 200:2012 2.44)

EXAMPLE 2 : Confirmation that performance properties or legal requirements of a measuring system are achieved.





P Verification of a measuring instrument: conformity assessment procedure (other than type evaluation) which results in the affixing of a verification mark and/or issuing of a verification certificate (VIML 2.09)

Initial verification: verification of a measuring instrument which has not been verified previously (VIML 2.12)





Subsequent verification: verification of a measuring instrument after a previous verification (VIML 2.13)

Note 1 Subsequent verification includes

- mandatory periodic verification,
- verification after repair, and
- voluntary verification.

Note 2 Subsequent verification of a measuring instrument may be carried out before expiry of the period of validity of a previous verification either at the request of the user (owner) or when its verification is declared to be no longer valid.





Calibration: operation that, under specified conditions, in a first step, establishes a relation between the quantity value with measurement uncertainties provided by measurement standards and corresponding indications with associated measurement uncertainties and, in a second step, uses this information to establish a relation for obtaining a measurement result from an indication.(VIMCo.hipration



Note 1 A calibration may be expressed by a statement, calibration function, calibration diagram, calibration curve, or calibrationtable. In some cases, it may consist of an additive or multiplicative correction of the indication with associated measurement uncertainty.





- Note 2 Calibration should not be confused with adjustment of a measuring system, often mistakenly called "self-calibration", nor with verification of calibration.
- Note 3 Often, the first step alone in the above definition is perceived as being calibration.





- Calibration consists of determining the deviation between the measurement value and the true value under specific conditions without making any changes.
- If necessary the instruments are adjusted after calibration.
- These weighing instruments have to be calibrated with calibrated weights in order to calculate the total. measurement uncertainty including the weights errors and the errors of the weighing instrument itself.
- In most of the countries the NIMs offer the calibration service directly or trough accredited laboratories.

# Calibration



### **Differences Calibration / Verification**

Calibration	Verification		
based on readability (d)	based on verification interval (e)		
no classification of the instrument	classification in accuracy class		
does not qualify the instrument	qualify the instrument pass or failed		
no tolerances fixed	MPE fixed by legal metrology (MPE)		
method through accreditation	method given by legal metrology		
results + measurement uncertainty	no measurement uncertainty		
use of calibrated weights	no measurement uncertainty		
must be done on site of use	can be done at another place		



# Thank You!



OIML Pilot Training Center 国际法制计量组织培训中心(示范)

# Test procedure of weighing performance, eccentricity, repeatability and warm-up

2016-07-20





- 1. Changeover Method
- 2. Pre-load
- 3. Test Procedure of weighing performance
- 4. Test Procedure of repeatability
- 5. Test Procedure of eccentricity
- 6. Test Procedure of warm-up



### What is legal metrology?

• Legal metrology is the application of legal requirements to measurements and measuring instruments "

### Weighing instrument

Measuring instrument that serves to determine the mass of a body by using the action of gravity on this body.

Where to find the legal requirements?

OIML Recommendations give the general Legal requirements





### **OVERVIEW OF R76**

### Structure of R76 non-automatic weighing instruments

TERMINOLOGY

[ 1 Scope

2 Principles of the Recommendation

🔀 3 Metrological requirements

4 Technical requirements for self- or semi-self-indicating instruments

5 Technical requirements for electronic instruments

6 Technical requirements for non-self-indicating instruments

7 Marking of instruments and modules

<u> 8 Metrological controls</u>

🔁 ANNEX A

🔁 ANNEX B

🔁 ANNEX C

🔁 ANNEX D

🔁 ANNEX E

🔁 annex f

[ 📐 ANNEX G

D BIBLIOGRAPHY

**Combination** of legal requirements of type evaluation and verification.



OIML Pilot Training Center 国际法制计量组织培训中心(示范)

### **OVERVIEW OF R76**

- A. Testing procedures for non-automatic weighing instruments
- B. Additional tests for electronic instruments
- C. Testing and certification of indicators and analog data processing devices as modules of non-automatic weighing instruments
- D. Testing and certification of digital data processing devices, terminals and digital displays as modules of non-automatic weighing instruments
- E. Testing and certification of weighing modules as modules of non-automatic weighing instruments
- F. Compatibility checking of modules of non-automatic weighing instruments
- G. Additional examinations and tests for software-controlled digital devices and instruments
  - 🔁 ANNEX A
  - 🔁 ANNEX B
  - 🔁 ANNEX C
  - 🔁 ANNEX D
  - 🔁 annex e
  - 🔁 ANNEX F
  - 🔁 ANNEX G
  - D BIBLIOGRAPHY



### Hierarchy for Verification of Mass and Weighing Metrology

National prototype of kilogram






Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

A.4.1.6 Indication with a scale interval smaller than *e* 

If an instrument with digital indication has a device for displaying the indication with a smaller scale interval (not greater than 1/5 *e*)





Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

**Condition:** For instruments with digital indication and without a device for displaying the indication with a smaller scale interval ( $\leq 1/5 e$ )



ACS-JJ(Tiger) : Max= 3 kg Min= 20 g e= 1 g n=3000

Without smaller scale interval



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

1. At a certain load, *L*, observe the indication, *I*, and record.



L = 10 gI = 10 g



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

2.Apply additional weights of say 0.1 e to the load receptor successively one at a time until the indication has changed unambiguously one scale interval (I + e).





Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

3. Record the additional load as  $\Delta L$ .



$$\Delta L = 0.5 \ e = 0.5 \ g$$



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

4. Use these values to calculate the error as per OIML R 76-1, Clause A.4.4.3.

e = 1 gE = I + 0.5e - DL - L

E = 0.010 + 0.5 - 0.5 - 0.010 = 0 g

If the change over point at zero as calculated above was  $E_0 = +0.1$  g , the corrected error at 10 g is:

$$E_{\rm c} = 0 - (+ 0.1) = -0.1 \, {\rm g}$$



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

**Procedure:** 

5. Use  $E_c$  and mpe to calculate the error OIML R 76-1, Clause 3.5.1.

Values of maximum permissible errors on initial verification

 $E_{\rm c} = 0 - (+ 0.1) = -0.1 \, {\rm g}$ 

Maximum permissible	For loads, <i>m</i> , expressed in verification scale intervals, <i>e</i>								
initial verification	Class I	Class II	Class III	Class IIII					
± 0.5 e	$0 \le m \le 50\ 000$	$0 \le m \le 5\ 000$	$0 \le m \le 500$	$0 \le m \le 50$					
± 1.0 e	$50\ 000 < m \le 200\ 000$	5 000 ≤ <i>m</i> ≤ 20 000	$500 < m \le 2\ 000$	$50 \le m \le 200$					
± 1.5 e	200 000 < <i>m</i>	$20\ 000 < m \le 100\ 000$	$2\ 000 \le m \le 10\ 000$	$200 < m \le 1\ 000$					



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

**Procedure:** 

5. Use  $E_c$  and mpe to calculate the error OIML R 76-1, Clause 3.5.1.

Values of maximum permissible errors on initial verification





Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

5. Use  $E_c$  and mpe to calculate the error OIML R 76-1, Clause 3.5.1.

Values of maximum permissible errors on initial verification

verification scale interval

Class III	0 ≤ <i>m</i> ≤ 500 <i>e</i>	0 <i>≤ m ≤</i> 500 g	mpe = $\pm 0.5$ g
$0 \le m \le 500$	500 e < m ≤ 2000 e	500 g < <i>m</i> ≤ 2000 g	mpe = $\pm 1.0$ g
$500 < m \le 2\ 000$ $2\ 000 < m \le 10\ 000$	2000 e <i>&lt; m ≤</i> Max	2000 g < <i>m</i> ≤ 3000 g	mpe = $\pm 1.5$ g

At the load of L = 10 g,  $E_c = 0 - (+ 0.1) = -0.1 g$ 



Clause: OIML R 76-1 Clauses A.4.4.3 and A.4.1.6

Equipment required: Equipment Under Test (EUT); Certified weights of 0.1 e to 10 e

#### **Procedure:**

5. Use  $E_c$  and mpe to calculate the error OIML R 76-1, Clause 3.5.1.

Values of maximum permissible errors on initial verification

verification scale interval

contention senie miter var			
Class III	0 ≤ <i>m</i> ≤ 500 <i>e</i>	0 <i>≤ m ≤</i> 500 g	mpe = $\pm 0.5$ g
$0 \le m \le 500$	500 <i>e &lt; m ≤</i> 2000 <i>e</i>	500 g < <i>m</i> ≤ 2000 g	mpe = $\pm 1.0$ g
$500 < m \le 2000$	2000 e <i>&lt; m ≤</i> Max	2000 g < <i>m</i> ≤ 3000 g	mpe = $\pm 1.5$ g
$2\ 000 < m \le 10\ 000$	At the load of $L = 10$	g, $E_{\rm c} = 0 - (+0.1) = -0.1$	g < mpe
			•

It satisfies the requirement of mpe at 10 g.



## 2 Pre-load



## # 2 Pre-load

**Clause:** OIML R 76-1 Clauses A.4.1.10 A.4.1.10 Preloading Before each weighing test the instrument shall be pre-loaded once to Max or to Lim if this is defined

**Equipment required:** Equipment Under Test (EUT) ;

Certified weights to the maximum load capacity of the instrument;

#### **Procedure:**

- 1. Apply a load equivalent to maximum capacity, Max.
- 2. Remove the weights in a similar manner.
- 3. Zero the instrument.





## **3 Weighing Test**



### Clause: OIML R 76-1, Clause A.4.4

**Equipment required:** Equipment Under Test (EUT) ; Certified weights to the maximum load capacity of the instrument:

Certified weights of 0.1 e to 10 e

### **Procedure:**

1. When determining the initial intrinsic error, at least 10 different test loads shall be selected, and for other weighing tests at least 5 shall be selected.

Including Max and Min (Min only if  $Min \ge 100 \text{ mg}$ )

Values at or near those at which the maximum permissible error (mpe) changes.

Record these test loads in column L of the verificationsheet and the appropriate mpe in the last column.



**Examples:** ACS-JJ(Tiger) is a class **(D)** Non-automatic weighing instrument with digital indication.

Max= 3 kg, Min= 20 g, e=1 g, n=3000

The test loads should be included as follows:

Load near the zero: 10 *e* =10 g Min: 20 *e*=20 g mpe change point: 500e= 500 g 2000e =2000 g Max: 3000 *e*=3000 g



**Examples:** ACS-JJ(Tiger) is a class **(III)** Non-automatic weighing instrument with digital indication.

Max= 3 kg, Min= 20 g, e=1 g, n=3000

The test loads should be included as follows:

	Load L (g)	Indication	on I (kg) t	Add. ∆L ∔	Load (g) t	Error t	'E(g) t	Corrected	error E∈ (g) †	mpe (± g)
Load near the zero —	→ 10	(*) 0.010	0.010	0.5	0.5	(*) 0.0	0.0	1	0.0	0.5
Min —	> 20	0.020	0.020	0.5	0.5	0.0	0.0	0.0	0.0	0.5
	100	0.100	0.100	0.5	0.5	0.0	0.0	0.0	0.0	0.5
	200	0.200	0.200	0.4	0.5	0.1	0.0	0.1	0.0	0.5
mpe change point —	► 500	0.500	0.500	0.5	0.6	0.0	-0.1	0.0	-0.1	0.5
	1000	1.000	1.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0
	1500	1.500	1.500	0.6	0.5	-0.1	0.0	-0.1	0.0	1.0
mpe change point —	2000	2.000	2.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0
	2500	2.500	2.500	0.5	0.5	0.0	0.0	0.0	0.0	1.5
Max —	3000	3.000	1	0.5	1	0.0	1	0.0	1	1.5



### **#3 Weighing Test**

2. Find the error at zero or near zero.



Using 10 *e* load as the zero point to take the instrument out of zero tracking range.



Add additional load 0.1 *e* at which the indication changes from one scale interval to the next.



## **#3 Weighing Test**

#### 3. Apply the test loads, increasing from minimum to maximum.



Example: Test in the first mpe change point



### **#3 Weighing Test**

#### 4. At each test load record the load, L, the indication, I, find the changeover point and record $\Delta L$ .

1 WEIGHING PERFORMANCE (A.4.4) (A.5.3.1) (Calculation of the error)

Application N°:	B219924740						
Type designation:	ACS-JJ(Tiger)						
Date:	2011.02.15						
Observer:	Zhong Ruilin			At start	At max	At end	
Verification			Temp:	23.0		23.7	°C
scale interval e:	1 g		Rel. h:	33.3			%
Resolution during test			Time:	9:05	9:13	9:20	
(smaller than e):	1		Bar. press	/		/	hPa
			(only class	( ( ( (			<b>Record the time</b>
Automatic zero-setting	and zero-tracking	g device is:					when the
Non-existent	Not in opera	tion $\times$ Out of w	orking range	In op	eration		maximum load
Initial zoro potting > 20		has been					
initial zero-setting > 20	70 UI WIAX.			70-1, A.4.	applied.		

 $\mathsf{E}=\mathsf{I}+\tfrac{1}{2}\:\mathsf{e}-\Delta\mathsf{L}-\mathsf{L}$ 

 $E_c = E - E_0$  with  $E_0 =$  error calculated at or near zero (\*)

Load L		Indicatio	Indication I (kg) Add. Load Error E (g			E (g)	Corrected	error E <sub>c</sub> (g)	mpe	
(g)		Ļ	1	¥	1	Ļ	Ť	Ļ	1	(± g)
10	(*)	0.010	0.010	0.5	0.5	(*) 0.0	0.0	/	0.0	0.5
20		0.020	0.020	0.5	0.5	0.0	0.0	0.0	0.0	0.5
100		0.100	0.100	0.5	0.5	0.0	0.0	0.0	0.0	0.5
200		0.200	0.200	0.4	0.5	0.1	0.0	0.1	0.0	0.5
500		0.500	0.500	0.5	0.6	0.0	-0.1	0.0	-0.1	0.5
1000		1.000	1.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0
1500		1.500	1.500	0.6	0.5	-0.1	0.0	-0.1	0.0	1.0
2000		2.000	2.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0
2500		2.500	2.500	0.5	0.5	0.0	0.0	0.0	0.0	1.5
3000		3.000	/	0.5	/	0.0	/	0.0	/	1.5



3000

3.000

0.5

/

### **#3 Weighing Test**

5. Remove the test loads, decreasing from maximum to zero load.

I WEIC (Calc	GHING PEI ulation of t	RF he	ORMANC error)	СЕ (А.4.4	4) (A.5.3	3.1)				Record	l the time
Application N	°:	<b>B</b> 2	1992474	D						and an	nbient
 Гуре designa	ition:	AC	CS-JJ(Tig	er)						temper	rature.
Date:		20	11.02.15								
Observer:		Zh	ong Ruil	in				Ats	start At max	At end	
erification	•						Ten	np: 2	3.0	<b>23.7</b> ℃	
scale interval	e:	1	1 g				Rel	. h: 3	3.3	%	
Resolution du	uring test						Tim	e: 9	:05 9:13	9:20	
smaller than	e):	1					Bar	. press	/	/ hPa	
	-						(onl	y class		<u> </u>	
E = I + ½ e - E <sub>c</sub> = E - E₀ w Load L	ΔL -L ith E₀ = en Indicatio	ror on l	calculate I (kg)	d at or r Add.	near zero Load	o (*) Error	E (g)	Corrected	error E₀ (g)	mpe	
(g)	I		<b>†</b>		(g) ↑	1	*	1	*	(± g)	
10 (*	°) 0.010		0.010	0.5	0.5	(*) 0.0	0.0	/	0.0	0.5	
20	0.020	-1	0.020	0.5	0.5	0.0	0.0	0.0	0.0	0.5	
100	0.100		0.100	0.5	0.5	0.0	0.0	0.0	0.0	0.5	
200	0.200		0.200	0.4	0.5	0.1	0.0	0.1	0.0	0.5	
500	0.500		0.500	0.5	0.6	0.0	-0.1	0.0	-0.1	0.5	
1000	1.000		1.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0	
1500	1.500		1.500	0.6	0.5	-0.1	0.0	-0.1	0.0	1.0	
2000	2.000		2.000	0.5	0.5	0.0	0.0	0.0	0.0	1.0	

0.0

0.0

1.5



6. At each test load record the load, *L*, the indication, *I*, find the changeover point and record  $\Delta L$ .

7. Calculate and record the error *E* where  $E = I + 0.5 e - \Delta L - L$  and the corrected error  $E_{\rm C}$  where  $E_{\rm C} = E - E_0$ .



E = 3000 + 0.5 - 0.5 - 3000 = 0 g



**#3 Weighing Test** 





### Note1:

A.4.2 Supplementary weighing test (4.5.1) For instruments with an initial zero-setting device with a range greater than 20 % of Max, a supplementary weighing test shall be performed using the upper limit of the range as zero point.

If the instrument has an initial zero-setting range > 20% a supplementary weighing test is required.

Note2:

A.4.4.1 Weighing test

1) At least 5 loads shall be selected.

2) Test loads selected shall include Max and Min (Min only if Min ≥ 100 mg)

3) Values at or near those at which the maximum permissible error (mpe) changes.



## Practical excersise:

## Test procedure

- 1. Note the load value L and indicated value I, as well as the additional load  $\Delta L$ .
- 2. Add weights according to previously defined load levels, until maximum load is reached. Always note L, I, and  $\Delta L$ . Only add weights, don't remove any.
- 3. Note the time.
- Remove weights according to previously defined load levels, until minimum is reached. Take notes. Only remove weights, don't add any.
- 5. Note time and temperature.
- 6. Calculate measurement errors.



## **4 Repeatability**



Clauses: OIML R 76-1, clauses 3.6.1 and A.4.10

1. For verification one series of weighings with about 0.8 Max is sufficient.

2. Three weighings on classes III and IIII or six weighings on classes I and II are necessary.

3. If the instrument is provided with automatic zero-setting or zero-tracking, it shall be in operation during the test. (A.4.10)

#### **Procedure:**

1. Determine the state of the automatic zero-setting device and zero-tracking device. Record by marking the appropriate box with an ×.





#### **Procedure:**

- 2. Determine the test load for the first set of weighings. This should be approximately 80% of Max. It is recommended that for a multi-interval instrument this test load should be near Max in the lowest partial range.
- 3. Record the time and ambient temperature.
- 4. Conduct a pre-load test . (A.4.1.10)
- 5. Apply the test load and record the indication, *I*.





#### **Procedure:**

6. Find the changeover point and record DL.



7. Calculate *E* using E = I + 0.5 e - DL - L and record.

E = 3000 + 0.5 - 0.5 - 3000 = 0 g

8. Remove the test load.

If the indication does not return to zero, reset instrument to zero.



Application N°:

5 REPEATABILITY (A.4.10)

B219924740

#### **Procedure:**

- 6. Repeat steps 5 to 8 as followings:
  3 times in all for class III, IIII
  6 times in all for class I, II.
  0.8 Max is sufficient
- 7. Calculate  $E_{max} E_{min}$  and record the result and the mpe for the test load.

	Туре	designation:	ACS-JJ(Tig	er)					•	
•	Date:	-	2011.02.25						•	
•	Obse	rver:	Ding Jing-a	an, Yao Hong				At start At n	hax At end	
	Verific	cation	-				Temp:	26.2	26.4	C
	scale	interval e:	1 g				Rel. h:			%
	Reso	lution during test	t				Time:	09:45		ī –
	(smal	ler than e):	1				Bar. press	/		hPa
							(only class	$(\square)$		-
								0		
	Autor	natic zero-settin	g and zero-tr	acking device i	s:					
	N	on-existent	$\times$ In opera	ition						
he										
пс		Load (weighing	1-10)	15	00 g	j Lo	ad (weighing 1	1-20 3	000	g
Ь			·					<b>I</b>		1-
u.	E= I +	⊦ 1/2 e - ΔL - L								
		Indication	Add. Load				Indication	Add. Load		
		of load I (kg)	ΔL (g)	E (g)			of load I (kg)	ΔL (g)	E (g)	
	1	1.500	0.5	0.0		11	3.000	0.5	0.0	
	2	1.500	0.5	0.0		12	3.000	0.5	0.0	
	3	1.500	0.5	0.0		13	3.000	0.5	0.0	
	4	1.500	0.5	0.0		14	3.000	0.5	0.0	
	5	1.500	0.5	0.0		15	3.000	0.5	0.0	
	6	1.500	0.6	-0.1		16	3.000	0.5	0.0	
	7	1.500	0.5	0.0		17	3.000	0.5	0.0	
	8	1.500	0.5	0.0		18	3.000	0.5	0.0	
	9	1.500	0.5	0.0		19	3.000	0.5	0.0	
	10	1.500	0.5	0.0		20	3.000	0.5	0.0	
		Emax - Emin (weig	phing 1 - 10)	0.1	g		Emax - Emin(weig	ghing 11 - 20)	0.0	g
										_
			mpe	± 1	g			mpe	± 1.5	g
			-							-
	C	heck if a) E $\leqslant$	mpe  (3.6 of	f R76-1)						
		b) Ema	ıx - Emin ≼ a	absolute value	of m	pe (3.6	6.1 of R76-1)			
		_								
	×	Passed	Failed							
	R	emarks:								

3.6 Permissible differences between results Single weighing result shall by itself not exceed the maximum permissible error for the given load.



5 **REPEATABILITY (A.4.10)** 

#### **Procedure:**

Pr	ocedure:	Applic	cation N°:	B219924740	) er)						
6.	Repeat steps 5 to 8 as followings:	Date: Obser	ver:	2011.02.25 Ding Jing-a	in, Yao Hong				At start At m	hax At end	
	3 times in all for class III, IIII	Verific scale	ation interval e:	1 g				Temp: Rel. h:	26.2	26.4	்ட %
	6 times in all for class I, II.	Resol (small	ution during test ler than e):	1				Time: Bar. press	09:45		hPa
	0.8 Max is sufficient							(only class	$(\mathbf{D})$		
		Auton	natic zero-settin on-existent	g and zero-tra $\overline{\times}$ In operation	acking device is tion	3:					
7.	Calculate $E_{max} - E_{min}$ and record the		Load (weighing	1-10)	150	)0 g	Lo	ad (weighing 1 <sup>-</sup>	1-20 3	000	]a
	result and the mpe for the test load.	E= I +	- 1/2 e - ΔL - L								
			Indication of load I (kg)	Add. Load ΔL (g)	E (g)			Indication of load I (kg)	Add. Load ΔL (g)	E (g)	I
		1	1.500	0.5	0.0		11	3.000	0.5	0.0	
		2	1.500	0.5	0.0		12	3.000	0.5	0.0	
		3	1.500	0.5	0.0		13	3.000	0.5	0.0	
		5	1.500	0.5	0.0		15	3.000	0.5	0.0	
		6	1.500	0.6	-0.1		16	3.000	0.5	0.0	
		7	1.500	0.5	0.0		17	3.000	0.5	0.0	
		8	1.500	0.5	0.0		18	3.000	0.5	0.0	
		9	1.500	0.5	0.0		19	3.000	0.5	0.0	

3.6.1 Repeatability Max difference can't be greater than the absolute value of the maximum permissible error

E <sub>max</sub> - E <sub>min</sub> (weighing 1 - 10) 0.1 g	E <sub>max</sub> - E <sub>min</sub> (weighing 11 - 20)
mpe ± 1 g	mpe
Check if a) E $\leq$  mpe  (3.6 of R76-1) b) Emax - Emin $\leq$ absolute value of mpe (3.6	.1 of R76-1)
× Passed Failed	

0.0

± 1.5 g

Remarks:



## Practical excersise:

## Test procedure

- 1. Add  $L = \frac{1}{2}$  maximum load and note the indicated value I as well as the additional load  $\Delta L$ .
- 2. Unload the weighing instrument.
- 3. Repeat steps 1 and 2 nine times.
- 4. Unload the weighing instrument and set indication to zero.
- Repeat steps 1 and 2 ten times with L = maximum load.
- 6. Calculate measurement errors.



## Eccentricity



•

## **#5 Eccentricity**

#### **Clauses** : OIML R76-1 3.6.2 and A.4.7

**Equipment:** Equipment Under Test (EUT) ;

Certified weights to the maximum load capacity of the instrument;

• Determine the state of the automatic zero-setting device and zero-tracking device. Record by marking the appropriate box with an  $\times$ .

<ul><li>3 ECCENTRICITY</li><li>3.1 Eccentricity us</li></ul>	Y (A.4.7) ing weights (A.4.7.1, 2 and 3)	<b>Record the time</b> and ambient
Application N°:	B219924740	temperature
Type designation:	ACS-JJ(Tiger)	
Date:	2011.02.25	
Observer:	Ding Jing-an, Yao Hong	At start At max At end
Verification		Temp: 26.2 °C
scale interval e:	1 g	Rel. h: 14.7 %
Resolution during test		Time: 9:32 9:35
(smaller than e):	1	Bar. Press / / hPa
		(only class 🕦 )
<ul> <li>(2) In case of "Yes" (1):</li> <li>(3) In case of "No" (2):</li> <li>Location of test loads:</li> <li>numbers which shall be</li> </ul>	A.4.7 and A.4.7.1 to A.4.7.4 have been app Description of eccentricity test(s) (see A.4.7 mark on a sketch (see an example below) th e repeated in the table below.	lied: Yes No .5) under "Remarks" e successive locations of test loads, using operation during the test.
Also indicate in the ske	etch the location of the display or of another i	perceptible part of the instrument
Automatic zero-setting	and zero-tracking device is:	ng range In operation



**Clauses** : OIML R76-1 3.6.2 and A.4.7

**Equipment:** Equipment Under Test (EUT) ;

Certified weights to the maximum load capacity of the instrument;

- The instrument has a load receptor having not more than four points of support.
- Divide the surface of the load receptor into four roughly equal quarter segments as outlined in diagrams below.





• Determine the individual surface areas of the load receptor where the loads are to be applied.

1	2
4	3

Location	Load L	Indication	Add. Load	Error	Corrected	mne († 0)
	(g)	l (kg)	ΔL (g)	E (g)	error E <sub>4</sub> (g)	mbe (7.8)
	C) 10	0.010	0,5	(°) 0.0	1	
1	1000	1.000	0.5	0.0	0.0	1
	C) 10	1	1	0 /	1	
2	1000	1.000	0.5	0.0	0.0	1
	(*) 10	1	1	0 /	1	
3	1000	1.000	0.6	-0.1	-0.1	1
	C) 10	1	1	0 /	1	
4	1000	1.000	0.5	0.0	0.0	1


#### **Procedure: A.4.7 Eccentricity tests (3.6.2)**

- 1. Do a pre-load test (A.4.1.10)
- 2. Zero instrument
- 3. Take a zero reading at either zero or 10 *e* at each location.
- 4. Add additional load 0.1 e at which the indication changes from one scale interval





5. Apply one-third Max plus maximum additive tare (if applicable) at the same location, with 10 *e* still on the load receptor if used.



6. Remove the 10 e if you are using it.





- 7. Record the indication, *I*.
- 8. Find the changeover point and record DL.



$$E = I + 0.5 e - DL - L$$
  
= 1000 g+0.5 g - 0.5 g -1000g  
= 0 g

- 9. Remove the load.
- 10. Repeat steps 6 to 11 at other locations in turn.
- 11. Calculate the error, *E*, where E = I + 0.5 e DL L and record. Calculate  $E_C$  where  $E_C = E E_0$ .



#### Note2:

A.4.7 Normally it is sufficient to determine the zero error only at the beginning of the measurement

On special instruments (accuracy class I, high capacity, etc.) it is recommended that the zero error be determined prior to each eccentricity loading.

Location	Load L (g)	Indication I(kg)	Add. Load ΔL (g)	Error E (g)	Connected error E <sub>e</sub> (g)	mpe (±g)
	(°) 10	0.010	0.5	(°) 0.0	1	
1	1000	1.000	0.5	0.0	0.0	1
	C) 10	1	1	$\circ$ /	1	
2	1000	1.000	0.5	0.0	0.0	1
	(*) 10	1	1	C) /	1	
3	1000	1.000	0.6	-0.1	-0.1	. 1
	C) 10	1	1	0 /	1	
4	1000	1.000	0.5	0.0	0.0	1



3.6.2.2 On an instrument with a load receptor having *n* points of support, with n > 4, the fraction 1/(n - 1) of the sum of the maximum capacity and the maximum additive tare effect shall be applied to each point of support.

*3.6.2.3* On an instrument with a load receptor subject to minimal off-centre loading (e.g. tank, hopper, etc.) a test load corresponding to 1/10 of the sum of the maximum capacity and the maximum additive tare effect shall be applied to each point of support.

*3.6.2.4* On an instrument used for weighing rolling loads (e.g. vehicle scale, rail suspension instrument) a test load corresponding to the usual rolling load, the heaviest and the most concentrated one which may be weighed, but not exceeding 0.8 times the sum of the maximum capacity and the maximum additive tare effect, shall be applied at different points on the load receptor.



#### Practical excersise:

### Test procedure

- 1. Note the load value L and indicated value I at zero/minimum, as well as the additional load  $\Delta L$ .
- Add 1/3 of the sum of the maximum load and additive tare to one subarea, determine and note the measurement error.
- 3. Repeat for other areas.
- 4. Calculate measurement errors.





# 6 Warm-up

#### A.5.2 Warm-up time test (5.3.5)

An instrument using electric power shall be disconnected from the supply for a period of at least 8 hours prior to the test.

The instrument shall then be connected and switched on and as soon

- as the indication has stabilized, the instrument shall be set to zero and the error at zero shall be determined.
- Calculation of the error shall be made according to A.4.4.3.
- The instrument shall be loaded with a load close to Max.
- These observations shall be repeated after 5, 15 and 30 minutes.
- Every individual measurement performed after 5, 15, and 30 minutes, shall be corrected for the zero error at that time.
- For instruments of class I, the provisions of the operating manual for the time following connection to the mains shall be observed.



# 6 Warm-up

#### Preparations

- Note general data (date, observer, temperature, time, state of zero-tracking device)
- Connect weighing instrument to power supply and switch it on
- <u>Do not</u> pre-load with maximum load
- Set indication to zero
- If zero-tracking device is active, add minimum load.



### 6 Warm-up

### Test procedure

- 1. Note the load value L and indicated value I as well as the additional load  $\Delta L$  at zero/minimum and maximum load.
- 2. Unload the weighing instrument but leave the minimum weight.
- 3. Repeat 1 and 2 after 5, 15, and 30 minutes.
- 4. Calculate measurement errors.



# Thank you for your attention!



中国北京 2016年7月18日-22日